

V3.7.0-20211013

Feature Updates

New Features

- Allows AP to be isolated from local networks.

Improvements

- Improved the connection of switching Wi-Fi Sta to Wi-Fi AP.
- Upgraded the WebView version of the T4H.

Fixed Problems

- The establishment of the channel connection between the Taurus and the server is abnormal when a 404 error is returned by the router.
- The T4H cannot use the mosaic card.
- The screen flashes and the grayscale loses when the T1-4G or T2-4G is used to load the screen.
- The screen flashes when cut-to-display text is played by using the T4H.
- The time is incorrect after the T4H is restarted.
- The TCB300 is frequently disconnected from the desktop software.

Remaining Problem

None

Required Software

Software Name	Software Version
ViPlex Handy	V3.6.0
ViPlex Express	V2.11.0

Related Information

<https://www.novastar.tech/downloads/>