

V2.1.2-20191217

Feature Updates

New Features

None

Improvements

None

Fixed Problems

Android:

When users switch the Wi-Fi mode of some terminals (such as TCB300) between Wi-Fi AP and Wi-Fi Station, the read back Wi-Fi status information is wrong.

Remaining Problems

None

Related Information

[ViPlex Handy LAN-Based Screen Management Software User Manual-V2.1.2.pdf](#)