

V3.4.0-20210426

Feature Updates

New Features

- Adapted to new models of network modules.
- Added a new networking scheme for the device. For details, contact the local technical support engineers.

Improvements

None

Fixed Problems

The screen occasionally displays blurred spots after the screen configuration file is sent.

Remaining Problems

None

Required Software

Software Name	Software Version
ViPlex Handy	V3.3.0
ViPlex Express	V2.8.1

Related Information

<http://www.novastar.tech/downloads/taurus/>